

Quintum Tenor AX, Version P104_12_10 Release Notes

This document describes the known issues for the Quintum Tenor AX series firmware version P104_12_10.

Known Issues

- **No Ringback on Device to Device Calls**—When calling from one device to another when the SIP message sequence is 183, 180, 183, the caller on the Quintum device will not hear ringing before the callee picks up the phone.
- **User Agent Header (UA) is “Quintum/1.0.0”**—The User Agent (UA) header sent by the Quintum Tenor AXM800 is “Quintum/1.0.0,” and does not include the model number and firmware version. This UA is also sent by other Quintum Tenor models.